

128-Point Vehicle Inspection

 **DRIVING SAFE**



This vehicle has

PASSED

the 128-point inspection

- | | |
|--|-------------------------------------|
| ✓ Body exterior fittings | ✓ Interior fittings |
| ✓ Engine compartment | ✓ Electrical controls |
| ✓ Front suspension,
steering and underframe | ✓ Rear suspension
and underframe |
| ✓ Exhaust system | ✓ Transmission |
| ✓ Fuel system | ✓ Brakes |
| ✓ Road test | ✓ Wheels and tyres |

Registration Example Car

Date 11/01/2017

Signed A. Mechanic

Dealership Information

Dealership Name: HPL Motors

Address: 396 Manchester Road, Oldham,
Greater Manchester, OL9 7PQ

Status: **Passed**

Car Information

Registration: SAMPLE 01

Make: Audi

Model: A3

Mileage: 47000

Colour: Black

VIN: 49640808304389809348902

Body Exterior Fittings

- | | |
|---|--|
| <input checked="" type="checkbox"/> Window and screen glass | <input checked="" type="checkbox"/> Door locks / Operation |
| <input checked="" type="checkbox"/> Bonnet hinges | <input checked="" type="checkbox"/> Fuel filler / Cover cap |
| <input checked="" type="checkbox"/> Bonnet catch | <input checked="" type="checkbox"/> Number plates |
| <input checked="" type="checkbox"/> Sunroof operation | <input checked="" type="checkbox"/> Convertible roof operation |

Interior Fittings

- | | |
|--|--|
| <input checked="" type="checkbox"/> Seat adjustment | <input checked="" type="checkbox"/> Seatbelts |
| <input checked="" type="checkbox"/> Boot / Tailgate lock | <input checked="" type="checkbox"/> Internal mirrors |

Engine Compartment

- | | | | |
|-------------------------------------|---------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Coolant level / Condition | <input checked="" type="checkbox"/> | Brake fluid |
| <input checked="" type="checkbox"/> | Coolant leaks | <input checked="" type="checkbox"/> | Engine oil level |
| <input checked="" type="checkbox"/> | Antifreeze | <input checked="" type="checkbox"/> | Oil leaking |
| <input checked="" type="checkbox"/> | Radiator cap | <input checked="" type="checkbox"/> | Engine mountings |
| <input checked="" type="checkbox"/> | Hoses / Pipes | <input checked="" type="checkbox"/> | Cold starting |
| <input checked="" type="checkbox"/> | Auxiliary drive belts | <input checked="" type="checkbox"/> | Fast idle (Cold) |
| <input checked="" type="checkbox"/> | Fuel pump / Pipes | <input checked="" type="checkbox"/> | Noise level (Cold) |
| <input checked="" type="checkbox"/> | Power steering oil level | <input checked="" type="checkbox"/> | Excess fumes / Smoke |
| <input checked="" type="checkbox"/> | Clutch fluid | <input checked="" type="checkbox"/> | Turbo / Supercharger
noisy or leaks |

Electrical & Controls

- | | | | |
|-------------------------------------|---------------------------------|-------------------------------------|---------------------------|
| <input checked="" type="checkbox"/> | Starting system / Ignition lock | <input checked="" type="checkbox"/> | Reverse / Fog lights |
| <input checked="" type="checkbox"/> | Battery condition | <input checked="" type="checkbox"/> | Auxiliary lights |
| | Battery voltages | <input checked="" type="checkbox"/> | Interior / Panel lights |
| <input checked="" type="checkbox"/> | 12.4v - Normal | <input checked="" type="checkbox"/> | Controls / Switches |
| <input checked="" type="checkbox"/> | 10.7v - Starting | <input checked="" type="checkbox"/> | Instruments |
| <input checked="" type="checkbox"/> | 14.1v - Charging | <input checked="" type="checkbox"/> | Horn |
| <input checked="" type="checkbox"/> | Headlights | <input checked="" type="checkbox"/> | Windows / Sunroof |
| <input checked="" type="checkbox"/> | Sidelights / Running lights | <input checked="" type="checkbox"/> | Wipers / Washers |
| <input checked="" type="checkbox"/> | Rear and number plate lights | <input checked="" type="checkbox"/> | Headlamp wash / wipe |
| <input checked="" type="checkbox"/> | Stop lights | <input checked="" type="checkbox"/> | Indicator / Hazard lights |
| <input checked="" type="checkbox"/> | Air conditioning operation | <input checked="" type="checkbox"/> | Electric door mirrors |

Front Suspension, Steering and Underframe

- | | |
|--|---|
| <input checked="" type="checkbox"/> Engine underside leakage | <input checked="" type="checkbox"/> Pipes / Hoses |
| <input checked="" type="checkbox"/> Steering and ball joints | <input checked="" type="checkbox"/> Dampers (Condition / Leaks) |
| <input checked="" type="checkbox"/> Steering rack / box | <input checked="" type="checkbox"/> Gaiters |
| <input checked="" type="checkbox"/> Chassis members | <input checked="" type="checkbox"/> Sub-frames / mountings |
| <input checked="" type="checkbox"/> Power steering (Operation) | <input checked="" type="checkbox"/> Suspension arms / mountings |
| <input checked="" type="checkbox"/> Wheel hubs / bearings | <input checked="" type="checkbox"/> Tie bars / Anti-roll bars |
| <input checked="" type="checkbox"/> Springs / Suspension units | |

Rear Suspension and Underframe

- | | |
|---|--|
| <input checked="" type="checkbox"/> Springs / Suspension bars | <input checked="" type="checkbox"/> Bump stops / Gaiters |
| <input checked="" type="checkbox"/> Anti-roll bar | <input checked="" type="checkbox"/> Wheel hubs / bearings |
| <input checked="" type="checkbox"/> Dampers / Bushes | <input checked="" type="checkbox"/> Pipes / Hoses |
| <input checked="" type="checkbox"/> Suspension arms / fixings | <input checked="" type="checkbox"/> Sub-frames / mountings |
| <input checked="" type="checkbox"/> Location rods / fixings | <input checked="" type="checkbox"/> Chassis members |

Transmission

- | | |
|--|--|
| <input checked="" type="checkbox"/> Fluid / Oil leaks | <input checked="" type="checkbox"/> Drive shaft assembly |
| <input checked="" type="checkbox"/> Cables / adjustments | <input checked="" type="checkbox"/> Universal / sliding joints |
| <input checked="" type="checkbox"/> Hydraulic system | <input checked="" type="checkbox"/> Backlash |
| <input checked="" type="checkbox"/> Linkage (Wear) | <input checked="" type="checkbox"/> Gaiters |
| <input checked="" type="checkbox"/> Casings | <input checked="" type="checkbox"/> Propshaft(s) fittings |
| <input checked="" type="checkbox"/> Mountings | <input checked="" type="checkbox"/> Bearings / Supports |
| <input checked="" type="checkbox"/> Clutch operation | |

Exhaust System

- | | |
|--|--|
| <input checked="" type="checkbox"/> Manifold | <input checked="" type="checkbox"/> Silencer(s) |
| <input checked="" type="checkbox"/> Pipes | <input checked="" type="checkbox"/> Heat shields / mountings |
| <input checked="" type="checkbox"/> Catalytic converter(s) | <input checked="" type="checkbox"/> Joints / Couplings |

Fuel System

- | | |
|--|---|
| <input checked="" type="checkbox"/> Tank | <input checked="" type="checkbox"/> Breather pipes |
| <input checked="" type="checkbox"/> Tank fixings | <input checked="" type="checkbox"/> Evidence of leaks |
| <input checked="" type="checkbox"/> Fuel lines | |

Brakes

- | | |
|--|---|
| <input checked="" type="checkbox"/> Master cylinder security | <input checked="" type="checkbox"/> Discs / Pads (if visible) |
| <input checked="" type="checkbox"/> Fluid leaks | <input checked="" type="checkbox"/> Handbrake operation |
| <input checked="" type="checkbox"/> Servo / Power system | <input checked="" type="checkbox"/> Flexible hoses |
| <input checked="" type="checkbox"/> Pedal and pad / linkage | <input checked="" type="checkbox"/> Pipes / Connections |

Wheels and Tyres

Status	Axle	Wheel
<input checked="" type="checkbox"/>	1	Front Left
<input checked="" type="checkbox"/>	1	Front Right
<input checked="" type="checkbox"/>	2	Rear Left
<input checked="" type="checkbox"/>	2	Rear Right

Axle	Wheel	Manufacturer	Size	Wheel Type	Tyre Type	Tread (mm)
1	Front Left	<u>Pirelli</u>	<u>195/65/15</u>	<u>Standard Alloy</u>	<u>Winter</u>	<u>6.2</u>
1	Front Right	<u>Pirelli</u>	<u>195/65/15</u>	<u>Standard Alloy</u>	<u>Winter</u>	<u>7.1</u>
2	Rear Left	<u>Pirelli</u>	<u>195/65/15</u>	<u>Standard Alloy</u>	<u>Winter</u>	<u>5.8</u>
2	Rear Right	<u>Pirelli</u>	<u>195/65/15</u>	<u>Standard Alloy</u>	<u>Winter</u>	<u>6.4</u>

Road Test

Test distance: 4.5 miles

Speed achieved up to: 30 mph

- | | |
|---|---|
| <input checked="" type="checkbox"/> Final drive operation / noise | <input checked="" type="checkbox"/> Steering effort |
| <input checked="" type="checkbox"/> Gearbox operation / noise level | <input checked="" type="checkbox"/> Hot restarting |
| <input checked="" type="checkbox"/> Engine performance | <input checked="" type="checkbox"/> Auto-changes / kick-down |
| <input checked="" type="checkbox"/> Engine noise | <input checked="" type="checkbox"/> Road holding / stability |
| <input checked="" type="checkbox"/> Overheating evidence | <input checked="" type="checkbox"/> Footbrake operation |
| <input checked="" type="checkbox"/> Instrument / control function | <input checked="" type="checkbox"/> Hand / park brake operation |
| <input checked="" type="checkbox"/> Suspension noise | <input checked="" type="checkbox"/> Cooling fan operation |
| <input checked="" type="checkbox"/> Warning lights | |

Rectifications Required

N/A

Engineers Comments

Car in great condition - enjoy!

Additional Information

Puncture repair kit in the glove compartment.

This report has been issued following a mechanical inspection of only the parts of the vehicle referred to in this report on the date specified on the cover sheet. This mechanical check can only describe or identify defects actually found and/or which are reasonably capable of being found upon an external visual consideration of the vehicle at the time of the check. We cannot be held and are not responsible for any latent defects discovered at a later date.